On power up, the DVI to HD-SDI Conversion Box will automatically detect the input format of the input.

Resolution
The factory default is 720p-59.94. If your SDI monitor does not support that mode and cannot display a picture to allow you to use the OSD, you can cycle through the output mode according to the following table:

PAL -> NTSC -> 720p30 -> 720p59 -> 720p60 -> 1080i23 -> 1080i24 -> 1080i25 -> 1080i29 -> 1080i30 -> 1080p23 -> 1080p24 -> 1080p25 -> 1080p29 -> 1080p30

Button 4 on the remote cycles foward and button 3 in reverse

DVI-D Input

5V Power
Connector

RS-422
Uplink Port

HD-SDI
Output

Supported Output Resolutions
The DVI to HD-SDI Conversion Box can output SD-SDI (NTSC or PAL) and HD-SDI (1080i, 1080p and 720p).

Supported Input Resolutions

Input	Resolution
DVI-D	All DVI-D interlaced and progressive scan formats up to 1920x1200

OSD and INFRARED REMOTE FUNCTIONS

The DVI to HD-SDI Conversion Box works with the Gefen RMT-4IR remote control.

Button 1 - Displays source and display information
Button 2 - Resets the Conversion Box to default settings (requires power cycle)
Button 3 - Cycles backwards through output resolutions
Button 4 - Cycles foward through output resolutions

* Both dip switches under the remote batter cover must be in the ON position to communicate with the conversion box

Restore I/O settings - Push down button 2 and then recycle power on the conversion box

1. Remove battery cover from the back of the RMT4-IR remote.

2. Verify that dip switches 1 & 2 are in the up (ON) position.

3. Insert the battery, hold the battery so that you can see the positive side facing up. The side that is not marked must be facing down.

4. Test the RMT4-IR remote by pressing ONLY one button at a time. The indicator light on the remote will flash once each time you press a button. WARNING: Do not press multiple buttons simultaneously and do NOT press buttons rapidly. These actions will cause the remote to reset and steps 1-4 will have to be repeated.

Note: The RMT4-IR ships with two batteries. One battery is required for operation, the second battery is complimentary.

The DVI to HD-SDI Conversion Box has an RS422 port that is used to upgrade the firmware of the unit. You can make the cable using the wiring diagram shown at the end of this document or purchase a cable form KK Systems.

HDVI-20
mini DIN8-M
Front View

V1 DB9-F
Front View

TX- (3)———(2) TXA
RX- (5)———(3) RXB

RX+ (8)
SIG GND (4)———(5) GND

Frame GND ◯———◯ Frame GND

Note: For a true RS422 connection, you can use an adapter made by KK Systems (Part Number K422-99). This adapter connects to the RS232 port on the PC and provides an RS422 connection on the other side. To connect the K422-99 to the DVI to HD-SDI Conversion Box, use a standard RS422 cable (Male DB9 to Male DB9 pin to pin). A true RS422 connection allows for a better connection and longer cables.

FIRMWARE UPDATE PROCEDURE

To upgrade the firmware of the DVI to HD-SDI Conversion Box, you need to have the DVI to HD-SDI Conversion Box RS422-PC cable. You also need to have the 3 files HDVI20.exe, HDVI-20_Uploader.bat and the HDVI-20 bin file (version 1.30 or higher, DO NOT USE ANY EARLIER VERSION) in your DOS directory. The DOS directory is the default directory when you launch the Command Prompt application under Windows.

1. Connect the DVI to HD-SDI Conversion Box RS422-PC cable to a COM port on your PC
2. Connect the DVI to HD-SDI Conversion Box to a DVI monitor
3. Force the DVI to HD-SDI Conversion Box in flash mode by pressing and holding the TV/Video on your infrared remote until the picture becomes red.
4. Double click on the HDVI20_Uploader.bat icon and enter the serial port connected to the
DVI to HD-SDI Conversion Box and hit ENTER
5. Enter the binary file name of the HDVI-20 bin file and hit ENTER
6. The screen will start showing you progress and it will quit after the upgrade is over.
7. Recycle power on the DVI to HD-SDI Conversion Box and go to the last menu and make sure the new firmware is installed.

Input .... DVI-D up to 1920x1200 progressive scan and 1080i formats

Output .... SD-SDI SMPTE 259M, HD-SDI SMPTE 292M and 720p-50

Power Supply .... 5V DC

Power Consumption .... 10 watts (max)

Dimensions .... 5.5"W x 1"H x 3.75"D

Shipping Weight .... 5 lbs.